

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

1594 West Nort
PO Box 145801

Kathleen Clarke Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

INSPECTION REPORT

			75~
Partial: XXX	Complete:	Exploration:	
Inspection Date	& Time	/2001 / 10:30a.m3:30p.	m.
I	Date of Last Ins	epection: 4/04/2001	

Iine Name: Sunnyside Refuse/Slurry County: Carbon Permit Number: 100 P								
Permittee and/or Operator's Name: Sunnyside Cogeneration Associates								
usiness Address: P.O. Box 10, East Carbon, Utah 84520								
ype of Mining Activity: Underground Surface XXX Prep. Plant Other								
ompany Official(s): Rusty Netz								
State Official(s): Bill Malencik Federal Official(s): None								
Veather Conditions: Clear, Temp 70's								
xisting Acreage: Permitted 310 Disturbed 202 Regraded Seeded Seeded								
tatus: Active XXX								

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	<u>N/A</u>	<u>COMMENTS</u>	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE		\Box	\Box	\Box
2.	SIGNS AND MARKERS	[X]	\Box	\Box	
3.	TOPSOIL	[X]	\Box	\Box	
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	[X]	\Box	[X]	\Box
	b. SEDIMENT PONDS AND IMPOUNDMENTS	[X]	П	[X]	\Box
	c. OTHER SEDIMENT CONTROL MEASURES	[X]	\Box	[X]	\Box
	d. WATER MONITORING	[X]	\Box	[X]	\Box
	e. EFFLUENT LIMITATIONS	[X]	\Box		\Box
5.	EXPLOSIVES	\Box	[X]	Ц	\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[X]	\Box	[X]	
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]	\Box	П	П
8.	NONCOAL WASTE	[X]	\Box	\Box	\Box
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	\Box	\Box	\Box	\Box
10.	SLIDES AND OTHER DAMAGE		\Box	П	\Box
11.	CONTEMPORANEOUS RECLAMATION	П	\Box	\Box	
12.	BACKFILLING AND GRADING	\Box	\Box	Ц	\Box
13.	REVEGETATION	П	Ц	\Box	\Box
14.	SUBSIDENCE CONTROL	\Box	[X]	\Box	\Box
15.	CESSATION OF OPERATIONS	\Box	П	П	\Box
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING	[X]	\Box	[X]	\Box
	b. DRAINAGE CONTROLS	\Box			. ∐
17.	OTHER TRANSPORTATION FACILITIES	\Box	П	\Box	\Box
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	\Box	\Box		
19.	AVS CHECK (4th Quarter- April, May, June)	[X]	\Box	[X]	
	AIR QUALITY PERMIT				- ∐
21	BONDING & INSURANCE	[]	[]	[]	[1

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/035

DATE OF INSPECTION: 5/10/2001

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

GENERAL COMMENTS

A partial inspection of the Sunnyside Cogeneration Mine was completed on 5/10/2001. No violations were issued as a result of this inspection.

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The mine was idle for 18 days to perform plant and environmental preventative maintenance. The mine started up this week. As related to the environmental part, this was the preventative spring maintenance work. The ditches, silt fences, refuse pile, berms, etc., were all maintained during the 18 day period.

Two problems were noted. A silt fence by the tipple was in need of repairs. The silt fence was partially down and was paced by the undersigned at about 10 feet. The silt fence drains into the runoff sediment pond. The silt fence was repaired before I left the mine. A ditch on the northeast side of the refuse pile was in need of repairs. All these were repaired before I left the mine site.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The majority of the site's diversions were clean and appeared to be capable of functioning as designed. Most of the diversions were regraded during the spring cleanup. One diversion by the northeast corner of the refuse pile was partially obstructed. It was repaired before I left the mine.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The disturbed area contains eleven impoundments, of which seven are sediment ponds. There are four slurry approved impoundments. Slurry cell one and two are non-MSHA impoundments and have been approved by the Division to store spoil from the refuse pile.

The east and west slurry cells are MSHA impoundments. These are monitored weekly. All slurry cells are inactive. This occurred when the Sunnyside Mine closed and no longer washed coal in 1994. No problems were noted. No impoundment was discharging during the inspection. This meets the coal rules.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The alternative sediment control on the lower site that drains into the railroad culvert needs some maintenance. This work was completed as part of the recent midterm. One silt fence by the tipple was in need of repairs. It was repaired immediately.

4D. HYDROLOGIC BALANCE: WATER MONITORING

Mr. Netz took the first quarter samples. Reviewed the results and no problems were noted. Mr. Netz entered the information in to the Division's data base. Sampling for the second quarter has not been performed by according to Mr. Netz. This meets the coal rules.

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: <u>C/007/035</u>

DATE OF INSPECTION: 5/10/2001

6. DISPOSAL OF EXCESS WASTE/FILLS/BENCHES

The permittee has an approved site to store spoil and tipple processing waste. Currently, spoil is stored in the decommissioned slurry cell as approved in the MRP. The waste is being placed in the slurry cell #1. The operation has moved into slurry cell #2. Both of the cells are currently being utilized for the storage of spoils. This meets the coal rules.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The permittee is currently mining the west slurry cell and contiguous refuse pile. No mining has started on the east slurry cell.

No hazardous conditions relative to the waste pile were noted during the inspection. This meets the coal rules.

16A. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

The roads have all been graded and maintained as part of the spring clean up.

19. AVS CHECK

Sunnyside Cogeneration still has a bond with Frontier. The last correspondence of record was in February, 2001, wherein Brian Bennett provided a progress report to Pamela Grubaugh-Littig. According to Mr. Netz, they still have a bond with Frontier. Although the company has committed to get a new bond.

Inspector's Signature:

Wm. J. Malencik #26

Date: May 15, 2001

Note:

This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc:

James Fulton, OSM Rusty Netz, Cogen Price Field office

O:\007035.SRS\Compliance\2001\p_0510.wpd